#### BY ORDER OF THE COMMANDER AIR MOBILITY COMMAND

IR MOBILITY COMMAND

AIR FORCE INSTRUCTION 21-103

AIR MOBILITY COMMAND
Supplement 2
15 APRIL 2002

Maintenance

EQUIPMENT INVENTORY, STATUS, AND UTILIZATION REPORTING

### COMPLIANCE WITH THIS PUBLICATION IS MANDATORY

**NOTICE:** This publication is available digitally on the AFDPO WWW site at:

http://afpubs.hq.af.mil.

OPR: HQ AMC/LGMMP (CMSgt Gerry Arens) Certified by: HQ AMC/LGM

(Col Rebecca J. Garcia)

Supersedes AFI 21-103 AMCS2,

20 December 1999

Pages: 14
Distribution: F

This publication supplements AFI 21-103, 20 July 1998. It addresses major command (MAJCOM) options and responsibilities. It applies to all Air Mobility Command (AMC) and Air Force Reserve Command (AFRC) units that provide direct support for AMC missions. All references to dash 21 (-21) equipment will also apply to C-17 On Board Loose Equipment OBLE. OBLE is essentially the same equipment as -21 equipment on other weapon systems. A vertical bar (|) indicates a change since the last edition.

#### SUMMARY OF REVISIONS

This revision contains minor policy changes related to equipment accountability. It also provides clarification for aircraft that do not have -21 TOs, added flare magazines as reparable items along with other weapon system specific items to repair tables including UH-1 equipment. Added requirement for Pope and Scott AFB maintenance units to support the aeromedical O2 bottle needs of the aeromedical crews at their bases. The revision also adds a requirement for electronic countermeasure tasked aircraft to carry extra M548 cans with empty magazines to facilitate enroute download. Eliminated C-20, C-21, and C-137 Command Unique Equipment Inventories.

- 9.1.2. The VC-25, C-32, C-20B/H, C-37 and C-40 do not have a -21 technical order. Units possessing these aircraft manage and control aircraft assets using local inventory control procedures and the AF Form 2692.
- 9.2.3. All units must maintain enough Alternate Mission Equipment (AME) to satisfy all the requirements in their Designed Operational Capability (DOC) statement.
- 9.3.4.1. (Added) Use AF Form 4076, **Aircraft Dash 21 Equipment Inventory**, to reflect specific aircraft configurations and identify -21 equipment installed on the aircraft. This form provides the means to control -21 equipment for aircraft while away from home station. Automated AF Form 4076 is authorized. C-9, KC-135, KC-10, and UH-1H aircraft are exempt from using AF Form 4076 within CONUS, use AF

Form 4076 or AF Form 2692 (transfers) as applicable for aircraft departing CONUS. The use of AF Form 4076 by AFRC will be determined by HQ AFRC as applicable.

- 9.3.4.2. (Added) Automated Inventory System. All units with G081 capability are required to maintain the total quantity of selected -21 equipment on hand in the G081 automated system. HQ AMC weapon system managers are responsible for inputting selected items in G081. Once loaded, the inventory must be updated as changes occur by the owning organization using screen 9015. Units should consider using other automated procedures, such as bar coding to conduct and track their inventory. Units that do not have G081 will inventory assigned -21 equipment in June of each year and send a list of shortages/overages to HQ AMC/LGM, or HQ AFRC/LGMA as applicable.
- 9.4.2.1. See Attachment 17 (Added), pages 7-15 of this supplement, in conjunction with the applicable -21 Technical Order (TO), for a listing of command-unique equipment by weapon system. Unless otherwise indicated, quantities listed are based on authorized items per aircraft. Only the MAJCOM approves waivers to maintain quantities other than these levels. C-141 units are required to maintain sufficient quantities of TO 1C-141B-21 alternate mission equipment line items 31-39 to meet their training and DOC statement requirements. Units will review DOC statements biannually to ensure sufficient levels are established.
- 9.6.3. The following tables list items, by weapon system, that have NF/ND expendability, recoverability, reparability codes (ERRC) and are considered equipment.

#### C-5 Aircraft

| Item              | NSN              | ERRC |
|-------------------|------------------|------|
| Tow ring assembly | 1620-00-494-3429 | NF3  |
| Adapter, tow ring | 1620-00-494-3429 | NF3  |

#### C-130 Aircraft

| Item                  | NSN              | ERRC |
|-----------------------|------------------|------|
| Winch cargo (Bulldog) | 1680-00-860-3934 | ND4  |
| Cable, static line    | 5180-00-104-5557 | NF4  |

- 9.6.3.2. NF/ND coded -21 equipment does not fall under the purview of the Air Force Equipment Management System (AFEMS). Accountability is a user responsibility.
- 9.6.4. The following tables list items, by weapon system, that have XD/XF expendability, recoverability, reparability codes (ERRC) and are considered reparable.

#### C-5 Aircraft

| Item                           | NSN              | ERRC |  |
|--------------------------------|------------------|------|--|
| Seat, instructor/student       | 1680-00-485-1216 | XD2  |  |
| Winch, heavy duty (C-133)      | 1680-00-856-9704 | XD2  |  |
| Winch assembly, cargo electric | 1680-00-343-7650 | XD2  |  |
| Winch assembly, hydraulic      | 1680-01-216-4525 | XD2  |  |

| Item                                   | NSN              | ERRC |
|--|------------------|------|
| Hoist, troop compartment               | 1680-01-206-1719 | XD2  |
| Regulator, oxygen bottle (walk around) | 1660-00-782-4697 | XD2  |
| Regulator, oxygen bottle (aft latrine) | 1660-00-095-1178 | XD2  |
| Bottle, portable oxygen                | 1660-00-605-7844 | XD2  |
| Hot beverage unit                      | 7330-01-242-4685 | XD2  |
| Coffee maker                           | 7310-01-205-7622 | XD2  |
| Flare magazine MJU-17A/A               | 5865-01-418-8760 | XF3  |

### C-9 Aircraft

| Item                    | NSN              | ERRC |
|-------------------------|------------------|------|
| Bottle, portable oxygen | 1660-00-605-7844 | XD2  |

## C-130 Aircraft

| Item                         | NSN              | ERRC |
|------------------------------|------------------|------|
| Winch, static line retriever | 1680-00-956-5221 | XD2  |
| Support, anchor cable        | 1560-00-607-2307 | XF3  |
| Flare magazine, MJU-34A      | 5865-01-4115278  | XF3  |
| Chaff magazine, MJU-33A      | 5865-01-411-5280 | XF3  |
| Bottle, portable oxygen      | 1660-00-605-7844 | XD2  |

## **KC-135 Aircraft**

| Item                    | NSN              | ERRC |
|-------------------------|------------------|------|
| Bottle, portable oxygen | 1660-00-605-7844 | XD2  |
| Hot Beverage unit       | 7310-00-151-6569 | XF3  |
| Water jugs              | 7330-00-537-5367 | XF3  |

## C-141 Aircraft

| Item                     | NSN              | ERRC |
|--------------------------|------------------|------|
| Bumper assembly (LH)     | 1560-00-906-3016 | XF3  |
| Bumper assembly (RH)     | 1560-00-691-1868 | XF3  |
| Winch, retriever         | 1680-00-835-6714 | XD2  |
| Winch, cargo (HCU9/A)    | 1680-00-956-5221 | XD2  |
| Ramp, auxiliary loading  | 1560-01-045-5724 | XD2  |
| Regulator, oxygen bottle | 1660-00-927-1996 | XD2  |
| Flare magazine, MJU-34A  | 5865-01-411-5278 | XF3  |

| Item                            | NSN              | ERRC |
|---------------------------------|------------------|------|
| Chaff magazine, MJU-33 (note 1) | 5865-01-411-5280 | XF3  |

NOTE 1: For C-141B Special Operations Low Level (SOLL) only.

### C-17 Aircraft

|   | Item                         | NSN              | ERRC |
|---|------------------------------|------------------|------|
|   | Flare magazine MJU-17A/A     | 5865-01-418-8760 | XF3  |
|   | Pump,Hand, Hydraulic         | 4320-01-300-3490 | XF3  |
|   | Adapter, Torque Wrench       | 5120-01-305-7241 | XF3  |
|   | Torque Wrench, Adapter       | 5120-01-303-4185 | XF3  |
|   | Lock, Aircraft Ground Safety | 1730-01-386-1257 | XF3  |
| I | Lock, Aircraft Ground Safety | 1730-01-458-5875 | XF3  |

- 9.6.4.1. Account for all SPARE XD and XF coded dash 21 recoverable items, and XF coded chaff/flare magazines on the Special Purpose Recoverables Authorized Maintenance (SPRAM) account (R25).
- 9.6.5. The following tables list items by weapon system, that are managed and controlled as expendables (XB3).

#### C-5 Aircraft

| Item                                     | NSN              | ERRC |
|--|------------------|------|
| Fire Ax                                  | 5110-00-814-2027 | XB3  |
| Kits, first aid                          | 6545-00-919-6650 | XB3  |
| Flare magazine retainer plate, MJU-17A/A | 5340-01-412-5616 | XB3  |
| M-548 Storage Container                  | 8140-00-739-0233 | XB3  |

## C-17 Aircraft

| Item                                     | NSN              | ERRC |
|--|------------------|------|
| Fire Ax                                  | 5110-00-814-2027 | XB3  |
| Kits, first aid                          | 6545-00-919-6650 | XB3  |
| Flare magazine retainer plate, MJU-17A/A | 5340-01-412-5616 | XB3  |
| M-548 Storage Container                  | 8140-00-739-0233 | XB3  |

## C-130 Aircraft

| Item                                   | NSN              | ERRC |
|--|------------------|------|
| Fire Ax                                | 5110-00-814-2027 | XB3  |
| Kits, first aid                        | 6545-00-919-6650 | XB3  |
| Flare magazine retainer plate, MJU-34A | 5342-01-394-0251 | XB3  |
| Chaff magazine retainer plate, MJU-33A | 5865-01-384-9404 | XB3  |
| M-548 Storage Container                | 8140-00-739-0233 | XB3  |

### **KC-135** Aircraft

| Item            | NSN              | ERRC |
|-----------------|------------------|------|
| Fire Ax         | 5110-00-814-2027 | XB3  |
| Kits, first aid | 6545-00-919-6650 | XB3  |

## C-141 Aircraft

| Item                                       | NSN              | ERRC |
|--|------------------|------|
| Fire Ax                                    | 5110-00-814-2027 | XB3  |
| Kits, first aid                            | 6545-00-919-6650 | XB3  |
| Flare magazine retainer plate, MJU-34A     | 5340-01-394-0251 | XB3  |
| Chaff magazine retainer plate,<br>MJU-33A* | 5865-01-438-9404 | XB3  |
| M-548 Storage Container                    | 8140-00-739-0233 | XB3  |

NOTE: For C-141B Special Operations Low Level (SOLL) only.

## **UH-1H Aircraft**

| Item                      | NSN               | ERRC |
|---------------------------|-------------------|------|
| Fire Extinguishers, halon | 4210-01-128-1673  | XB3  |
| Main Rotor tie-down       | 1730-00-427-7939  | XB3  |
| Tail Rotor tie down       | 1680-00-967-1821  | XB3  |
| Tail Pipe covers          | 1730-00-539-6120  | XB3  |
| Engine Inlet cover (RH)   | 1560-00-168-6045  | XB3  |
| Engine Inlet cover (LH)   | 1560-00-168-6046  | XB3  |
| Pitot Cover               | 1730-00-674-1946  | XB3  |
| Nose Cover                | Local Manufacture | XB3  |

| Item             | NSN               | ERRC |  |
|------------------|-------------------|------|--|
| Map Holder       | Local Manufacture | XB3  |  |
| 4-man troop seat | 1680-00-498-2991  | XB3  |  |
| Safety Belts     | 1680-01-457-6922  | XB3  |  |
| Stanchion Assy   | 1680-00-941-8708  | XB3  |  |
| Ring Assy        | 5306-00-967-1775  | XB3  |  |
| First Aid Kit    | 6545-00-919-6650  | XB3  |  |

- 9.7. HQ AMC/LGM is the office of primary responsibility (OPR) for active units
- 9.7.1. (Added) Conditions may occur (i.e., equipment is lost, replaced, and then later recovered) that result in overages of assets. These overages can go undetected by the -21 item manager until the annual inventory is accomplished (see **9.3.4.2.** (Added)); therefore, -21 equipment sections may have overages during unscheduled inspections, audits, and inventories. All -21 sections, or equivalent, may have on hand up to 10 percent over the total authorized level of ERRC NF, ND, XD, XF and XB3 assets. The intent of this overage allowance is to compensate for fluctuations of on-hand equipment between inventories. It is not intended to authorize units to arbitrarily increase equipment authorizations. Report all overages during annual inventory to HQ AMC/LGM.
- 9.9.2. Sortie Support Flight manages and maintains -21 equipment and ensures aircraft configuration changes are documented, as necessary, in the G081 automated system. Exception: For the C-17, this is a Sortie Generation Flight function.
- 9.9.4. Sortie Support Flight maintains the CA/CRL or SPRAM listings.
- 9.9.4.3. Units must report any shortages by message to HQ AMC/LGM and HQ AFRC/LGMA, as applicable for corrective actions. Ensure the accountable records (i.e., custody account (CA)/custody receipt listing (CRL)) are annotated to show the inventory has been completed. The appropriate MAJCOM will direct the redistribution of assets as required.
- 9.9.4.3.1. (Added) Equipment Identification. Identifying -21 equipment (using stencils) is necessary to properly inventory and maintain control of assets by the owning organization. The identification system is also useful to help identify ownership of equipment removed off station due to mission requirements. If equipment is properly and clearly marked it will make it easier to identify the owning organization in order to facilitate equipment return. Place the stencil in a conspicuous location so that it is readily identifiable. Mark equipment that is to small to allow you to mark the equipment (that is too small to stencil with black paint) with a black permanent marker, or an engraver if possible. If the item is still too small for a marker or engraver, then disregard marking it. HQ AMC/LGM (Active Duty and Reserve Associate) is waiver authority for this requirement. The following procedures apply for marking aircraft -21 equipment:
- 9.9.4.3.1.1. (Added) All organizations, except C-5, KC/EC-135, C-17, and C-141 units, will stencil their organization identifier (e.g., 317AG, 43AW, etc.) on each piece of -21 equipment, using **black paint only**.
- 9.9.4.3.1.2. (Added) The C-5, KC/EC-135, C-17, and C-141 organizations will stencil their organization identifier (e.g., 439AW, 60AMW, 459AW, 62AW, etc.) on each piece of -21 equipment (Example: 319 ARW Black letters on yellow background) using the following color(s) code:

| AMC Units          | AFRC Units                   |
|--------------------|------------------------------|
| 6 ARWBlack/White   | 433 AW—Purple                |
| 19 ARGBlack/Blue   | 434 ARWsee NOTE 2            |
| 22 ARWBlack/Red    | 439 AWLight Blue             |
| 60 AMW—Blue        | 445 AW—Red                   |
| 62 AW—Green        | 452 AMW (452 AGS) Yellow     |
| 92 ARWBlack/Orange | 452 AMW (752 AGS) see NOTE 2 |
| 305 AMW—White      | 459 AW—Black                 |
| 436 AW—Brown       | 507 WGsee NOTE 2             |
| 437 AW—Orange      | 916 ARWsee NOTE 2            |
|                    | 927 ARWsee NOTE 2            |
|                    | 931 ARGsee NOTE 2            |
|                    | 940 ARWsee NOTE 2            |

- **NOTE** 1: Mark items that are too small to stencil with the color(s) only. Applied paint will not interfere with the operation of the item.
- **NOTE 2**: AFRC KC-135 units will stencil their organizational identifier on each piece of -21 equipment using their designated tail stripe color code.
- 9.9.5. The -21 equipment section within the Sortie Support Flight is the base-level organization responsible for daily asset management and control of aircraft -21 equipment. For those units that do not have -21 sections or sortie support flights, the activity that is responsible for aircraft generation launch and recovery operations will perform these duties, i.e. Sortie Generation Flight for C-17s. The -21 equipment section will:
- 9.9.5.1. (Added) Configure aircraft according to directives.
- 9.9.5.2. (Added) Ensure delivery and installation of additional -21/AME equipment based on mission requirements and additional equipment remarks on the flying schedule (as applicable).
- 9.9.5.3. (Added) Update the automated inventory system as changes occur for -21 equipment using the quantities listed on the AF Form 4076.
- 9.9.5.4. (Added) Maintain the most current AF Form 4076 (aircraft away from home station) and any other documentation pertaining to the recovery of lost or removed -21 equipment for that aircraft.
- 9.9.5.4.1. (Added) Contact the owning aircraft QA Weight and Balance program manager when -21 equipment is added to or removed from the aircraft away from home station if the weight difference changes by 2 pounds for aircraft under 25K or 5 pounds for aircraft over 25K basic weight in accordance with TO 1-1B-50. A weight and balance adjustment will be required.
- 9.9.5.5. (Added) Ensure aircraft departing home station have a current inventory of installed -21 equipment. C-9, KC-10, KC-135, and UH-1H aircraft are exempt from using AF Form 4076, use AF Form 4076 or AF Form 2692 (transfers) as applicable for aircraft departing CONUS. Initiate an AF Form 4076 in duplicate prior to aircraft departing home station.

- 9.9.5.5.1. (Added) Place the original copy and at least two extra blank copies in the aircraft forms binder.
- 9.9.5.5.2. (Added) Keep a duplicate copy of the AF Form 4076 on file as a source document.
- 9.9.5.6. (Added) Perform an inventory check as soon as possible after block-in of home station aircraft to determine if assets are missing, and complete the final check block on the AF Form 4076.
- 9.9.5.7. (Added) Check the AFTO Forms 781A for any -21 equipment discrepancies and initiate action to replace/repair any missing/broken equipment.
- 9.9.5.8. (Added) The -21 section, or equivalent, as listed above, is not responsible for maintaining or storing chaff/flare magazines or retainer plates. These items are maintained by ECM shop and when pre-loaded are stored and delivered by munitions flight within the maintenance or component repair squadron (as applicable). These items were added to the aircraft equipment list as a vehicle to track and transfer them.
- 9.9.5.9. (Added) -21 section, or equivalent as listed above, is responsible for storage and delivery of serviceable Portable (O2) Oxygen Walk Around Bottles to meet all mission needs including aeromedical missions. The -21 function is responsible for storage but is not responsible for repair. The Electro/Environmental Shop or equivalent function has responsibility for repair/replacement of the oxygen regulator and bottle assembly to include all inspections and hydrostatic tests in accordance with applicable technical data. For AE units at Pope and Scott AFB, to include AE Crews embedded in Mobile Air Staging Facilities (MASIF), the -21 section or equivalent sortic generation activity, will be responsible for storage of bottles, but the AE unit is responsible for issue, receipt and accountability of their AE bottles that are required for operational/training missions or deployments to support their DOC statement. Enough bottles will be maintained to support crewmembers in each DOC tasked crew.
- 9.9.5.10. (Added) Loan -21 equipment to transient AMC aircraft or other AMC units when such equipment is available and required to continue the aircraft mission. Annotate the AF Form 4076 accordingly in the next open check column to show the increase of equipment. Ensure the location and date is annotated in the appropriate blocks at the top of the column. Additionally, document the AFTO Form 781A so the assets can be returned. The entry will include mission number, the equipment loaned, unit loaning the equipment, point of contact for returning equipment, (i.e., name, DSN, etc.) and returning unit (i.e. McGuire, McChord). Retain a record in a suspense file until return of equipment. If equipment is not returned within 30 days from the date of loan, notify the unit/home station that borrowed the equipment via message with info copy sent to HQ AMC/LGM or HQ AFRC/LGMA.
- 9.9.5.11. (Added) The -21 section, or equivalent, is responsible for storage and delivery of Prepositioned Aeromedical Emergency Evacuation Equipment (PAEEE). Use of PAEEE is governed by AMCI 11-208, *Tanker/Airlift Operations*. PAEEE must be returned to the appropriate en route location as soon as possible.
- 9.9.5.12. (Added) Return loaned -21 equipment to the owning organization as soon as possible, but not later than 30 days after the date loaned.
- 9.9.5.13. (Added) Maintain AF Forms 1297, **Temporary Issue Receipt,** in the aircraft -21 equipment folder for equipment removed at AMC en route stations until returned. AMC Enroute units must ensure -21 equipment folders are current and any equipment removed is properly documented and accounted for. With the exception of prepositioned equipment, return all -21 equipment removed from transient aircraft to the owning organization as soon as possible but not later than 30 days after the date removed from the aircraft.

- 9.9.5.14. (Added) Be accountable for starter breech caps used on installed engines of C-135 series aircraft. Breech caps not installed on aircraft mounted engines will be stored by the -21 section.
- **9.14.** HQ AMC/LGM, and HQ AFRC/LGMA, must coordinate with each other to make equipment adjustments, if required.
- 9.14.1. Organizations will immediately report shortages affecting mission integrity by message to HQ AMC/LGM, HQ AFRC/LGMA and info NAFs (as applicable). Hold disposition of overages and requisitions to replace shortages in abeyance pending HQ AMC/HQ AFRC/HQ determination. If the applicable MAJCOM instructs you to requisition shortages based on authorization levels, initiate report of survey on each shortage.
- 9.16.2. AMC aircraft tasked with countermeasures will carry empty M-548 cans as on board loose equipment to facilitate en route countermeasures download. AMC aircraft will carry empty countermeasures magazines stored in M-548 containers.

#### **Attachment 17 (Added)**

#### **COMMAND-UNIQUE EQUIPMENT**

A17.1. The following tables identify assets that have been identified as command-unique equipment in conjunction with the applicable -21 weapon system TOs. Applicable units will maintain quantities authorized by this attachment. Unless otherwise indicated, quantities listed are based on authorized items per aircraft. Only MAJCOM HQ as applicable, approves waivers to maintain quantities other than these levels. Assign local line item numbers that do not conflict with -21 TOs.

### **C-5 COMMAND-UNIQUE EQUIPMENT**

SECTION I, Maintenance Safety and Protective Equipment (MSPE): N/A

SECTION II, Alternate Mission Equipment (AME): N/A

SECTION III, Crew and Passenger Support Equipment (CPSE): N/A

#### C-9A COMMAND-UNIQUE EQUIPMENT

SECTION I, MSPE: N/A SECTION II, AME: N/A

SECTION III, CPSE: N/A

#### C-9C COMMAND-UNIQUE EQUIPMENT

SECTION I, (MSPE): N/A

| SECTION II, AME                             |                   |          |
|---|-------------------|----------|
| Nomenclature                                | Part Number       | Quantity |
| Copier, Xerox with 81/2" paper tray         | XEROX 1025        | 1        |
| Typewriter, electric, IBM Wheel Writer      | 1500              | 1        |
| Safe, combination                           | 7110-00-920-9339  | 1        |
| SECTION III, CPSE                           |                   |          |
| Nomenclature/Part Number                    | Part Number       | Quantity |
| Color TV, Panasonic (20") with remote       | PV-M2053          | 1        |
| Stereo, alpine, with CD shuttle             | 5952ZX            | 1        |
| Cordless headset, stereo                    | JCK/200-A1        | 1        |
| Digital clock, 2 position wood (Gulfstream) | P/N SC41503006-03 | 1        |
| Emerson microwave                           | MT3060            | 1        |

### KC-10 COMMAND UNIQUE EQUIPMENT

SECTION I, MSPE: N/A

SECTION II, AME (*NOTE*: Requires CCM modified aircraft.)

| Nomenclature                   | Part Number | Quantity |
|--------------------------------|-------------|----------|
| PSK2 JTFCCM/CS for Yokota AB   | N/A         | A/R      |
| PSK3 JTFCCM/CS for McGuire AFB | N/A         | A/R      |
| SECTION III, CPSE: N/A         |             |          |

### C-17 COMMAND-UNIQUE EQUIPMENT

SECTION I, MSPE: N/A

SECTION II, AME (*NOTE*: Requires CCM modified aircraft.)

| Nomenclature                   | Part Number | Quantity |
|--------------------------------|-------------|----------|
| PSK2 JTFCCM/CS for Yokota AB   | N/A         | A/R      |
| PSK3 JTFCCM/CS for McGuire AFB | N/A         | A/R      |
| SECTION III, CPSE: N/A         |             |          |

## C-130 COMMAND-UNIQUE EQUIPMENT

SECTION I, MSPE: N/A

SECTION II, AME: N/A

SECTION III, CPSE: N/A

### EC-135N/Y COMMAND-UNIQUE EQUIPMENT

SECTION I, MSPE: NA

SECTION II, AME

| Nomenclature                     | Part Number    | Quantity |
|----------------------------------|----------------|----------|
| Section A (Communications Suite) |                |          |
| Fax machine, cryptic 10          | 707336-801     | 2        |
| Disc drive                       | VHP7907A       | 1        |
| Processor                        | ES293-0000-1   | 1        |
| Computers laptop/Grid, Hetras /  | Grid 1537A     | 2        |
| PBX Telephone switch board       | JB3614VTT      | 1        |
| Telephone (black)                | ETL 102-0000-1 | 1        |
| Safe                             | Local Purchase | 1        |
| Section B (Galley)               |                |          |
| Telephone (black)                | ETL 102-0000-1 | 1        |

| Section C               |                |   |  |
|-------------------------|----------------|---|--|
| Telephone (black)       | ETL 102-0000-1 | 2 |  |
| Telephone (red secure)  | ETL 101-0000-3 | 4 |  |
| Section D               |                |   |  |
| Telephone (black)       | ETL 102-0000-1 | 2 |  |
| Telephone (red secure)  | ETL 101-0000-3 | 4 |  |
| Shredder, Destroy-it    | D7460          | 1 |  |
| Section E               |                |   |  |
| Telephone (black)       | ETL 102-0000-1 | 1 |  |
| Telephone (red, secure) | ETL 101-0000-3 | 1 |  |

# SECTION III, CPSE

| Nomenclature                                    | Part Number       | Quantity |
|---|-------------------|----------|
| Section A                                       |                   |          |
| Wood table                                      | Local Manufacture | 1        |
| Cloth seats, 16G, series 900                    | Local Manufacture | 4        |
| Communications Suite                            |                   |          |
| Leather seats, 16G, series 500                  | Local Manufacture | 2        |
| Section B (Galley)                              |                   |          |
| Cloth seats, 16G, series 900                    | Local Manufacture | 4        |
| Vinyl jump seats                                | Local Manufacture | 2        |
| Sink (dual), 36 inch                            | Local Purchase    | 1        |
| Full range, GE, 36 inch range                   | Local Purchase    | 1        |
| Oven, GEJTP17 convection, 36 inch               | Local Purchase    | 1        |
| Range hood w/light & fan, GE 36 inch range hood | Local Purchase    | 1        |
| Microwave, Nordskog                             | 50361/50466       | 1        |
| Trash compactor, Kitchenaid TMC28               | Local Purchase    | 1        |
| Bun warmer, thermador                           | Local Purchase    | 1        |
| Hot cups, standard                              | Local Purchase    | 2        |
| Coffee pot, (Mr Coffee)                         | Local Purchase    | 1        |
| Water System                                    |                   |          |
| 40 gallon water tank,                           | Local Manufacture | 1        |
| 10 gallon hot water heater, GE                  | Local Purchase    | 1        |
| Water pump 28VDC, model 36950-2                 | Local Purchase    | 1        |
| Section C                                       |                   |          |
| Wood table                                      | Local Manufacture | 2        |

| Cloth seats, 16G, series 900   | Local Manufacture | 4  |
|--------------------------------|-------------------|----|
| Wall clocks, 12 inch           | Local Purchase    | 2  |
| Section D                      |                   |    |
| Cloth seats, 16G, series 900   | Local Manufacture | 10 |
| Wood table                     | Local Manufacture | 1  |
| Leather seat, 16G, series 500  | Local Manufacture | 1  |
| Stereo (PA), Sony              | Local Purchase    | 1  |
| Wall clocks, 12 inch           | Local Purchase    | 2  |
| Section E                      |                   |    |
| Leather seats, 16G, series 500 | Local Manufacture | 2  |
| Wood table                     | Local Manufacture | 1  |
| Vacuum cleaner, Sears 12hr     | Local Purchase    | 1  |

**NOTE:** Series seats are from Aircraft Modular Systems

## KC-135 COMMAND-UNIQUE EQUIPMENT

SECTION I, MSPE: N/A

SECTION II, AME: N/A

SECTION III, CPSE: N/A

## C-141 COMMAND-UNIQUE EQUIPMENT

SECTION I, MSPE: N/A

SECTION II AME

| SECTION II, AME   |                   |          |  |
|---|-------------------|----------|--|
| Nomenclature  | Part Number       | Quantity |  |
| Table   | Local Manufacture | A/R      |  |
| DV Step Set (1 front, 1 back)                             | Local Manufacture | A/R      |  |
| Support Curtain   | Local Manufacture | A/R      |  |
| Carpet, Roll  | AY6026-55880      | A/R      |  |
| Curtain, Weather  | Local Manufacture | A/R      |  |
| Seat, Enhanced Triple, LH (Per Primary Assigned Aircraft) | 838005-401        | 4        |  |
| Seat, Enhanced Triple, RH (Per Primary Assigned Aircraft) | 838005-402        | 4        |  |
| Seat, Enhanced Triple                                     | Model 940-02BR-3R | A/R      |  |

# SECTION III, CPSE

| Nomenclature  | Quantity |
|---|----------|
| Protector, head                                       | A/R      |
| Civic Leader Kit (with pallet mounted DV double seats | A/R      |
| Joint Task Force Command & Control Module (JTFCCM)    | A/R      |
| CINC Kit  | A/R      |

JAMES L. LEMONS, Colonel, USAF Deputy Director of Logistics